

10450 Stancliff Rd, Ste 210

Houston, TX 77099 **T:** +1 281 530 5656 **F:** +1 281 530 5887 **www.alsglobal.com**

Sample Receipt Checklist

Work Order ID: HS19031346 27 Mar 2019 11:05 Date/Time received: Client name: InterContinental Terminal Company Received by: Patrick Salome Completed/By: 27 Mar 2019 11:40 Jared R. Makan **Reviewed/By:** 27 Mar 2019 16:53 Bernadette A. Fini eSignature Date/Time eSignature Date/Time Carrier name: ALS Courier Matrices: Water Yes □ No Not Present Shipping container/cooler in good condition? ✓ Not Present Custody seals intact on shipping container/cooler? Yes ∏ No ✓ Not Present Yes **Custody seals intact on Sample bottles?** Yes No ✓ Not Present VOA/TX1005/TX1006 Solids in hermetically sealed vials? Chain of custody present? ✓ Yes No 2 Page(s) Chain of custody signed when relinquished and received? COC ID(s): 197665, 197620 ✓ Yes **✓** Yes Samplers name present on COC? ✓ Yes Chain of custody agrees with sample labels? ✓ Yes Samples in proper container/bottle? ✓ Yes Sample containers intact? **✓** Yes Sufficient sample volume for indicated test? **✓** Yes No All samples received within holding time? ПNо Container/Temp Blank temperature in compliance? ✓ Yes Temperature(s)/Thermometer(s): 1.8c/1.8c, 1.9c/1.9c UC/C IR25 **Cooler Information:** 1 Cooler(s), 44778, 44136 03/26/2019 12:45 Date/Time sample(s) sent to storage: Water - VOA vials have zero headspace? ✓ Yes No No VOA vials submitted ✓ Yes Not Applicable Water - pH acceptable upon receipt? No pH adjusted? ✓ No Not Applicable Yes pH adjusted by: Sample collected 03/26/2019 at 10:00 contains a layer of oil above the sample. Login notes: **Client contacted:** Date contacted: Person contacted: Regarding: Contacted by: Comments: **Corrective action:**

27 Mar 2019 Page 1 of 1